

VEHICLE INSPECTION REPORT

LT17YGR

Ford Transit 350 2.0 TDCI 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 24/03/2017

Year 2017

Mileage 136,752 Miles
Warranted

Fuel Type Diesel

Colour GREEN

VIN WF0XXXTTGXGY82990

Body Style Panel Van LWB

MOT Due 11/01/2026

CAP Clean £3,525.00

CAP Average £2,975.00

CAP Below £2,275.00

Gearbox MANUAL

Gears 6

SIDE LOADING DOOR, E/WINDOWS

Tyres

NSF


NSR


OSF

OSR


Spare

Photos





Condition Check



Damage Photos



1: Front TowEye Cvr
Missing
Replace



2: Wing nsf
Scratched
Over 25mm Not Thru Paint



3: Panel Rear
Dented
Between 10mm + 30mm



4: Bumper Rear Moulding
Broken
Replace



5: Bumper Rear Moulding
Broken
Replace



6: Sill ns
Rusted
Over 5mm



7: Seat Base Cover osf
Holed
Over 3mm



8: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average Average	Odour	Average No
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK