

VEHICLE INSPECTION REPORT

PE17HNK

Daf CF 440

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 06/03/2017

Year 2017

Mileage 1,512,848 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G149152

Body Style Tractor Unit

Service history Yes

MOT Due 30/04/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

COLLECTED AS NON-RUNNER, ENGINE, BRAKE & WINDOW FAULTS, WARNING LIGHT ON DASH

Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3




OSO4

Features

- Cruise control
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bumper Front
Chipped
Multiple Chips

2: Panel Front
Cracked
Replace



3: Bumper Front
Dented
With Paint Damage

4: Qtr Panel Moulding os
Scratched (Painted)
Over 25mm Thru Paint



5: Panel Rear
Dented
With Paint Damage

6: Door nsf
Dented
Between 10mm + 30mm



7: Door nsf
Chipped
Multiple Chips

8: Bumper Front
Dented
With Paint Damage



9: Seat Base Cover nsf
 Holed
 Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		