

VEHICLE INSPECTION REPORT

PK67VFN

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 09/11/2017

Year 2017

Mileage 1,098,419 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G181969

Body Style Tractor Unit

Keys 1

Service history Yes

MOT Due 31/03/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

WARNING LIGHT ON DASH SURROUND CAMERA SYSTEM

Tyres

NSF

NSI1

NSI2

NSI3

NSI4

OSF

OSI1

OSI2

OSI3

OSI4

Spare

NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3





OSO4

Features

- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Radio/CD
- Cloth seat trim
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front Moulding
Broken
Replace

4: Door Mirror Assy osf
Broken
Replace



5: Door osf
Chipped
Multiple Chips

6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Qtr Panel Moulding ns
Broken
Replace

8: Door nsf
Dented
With Paint Damage



9: Bumper Front
Dented
With Paint Damage

10: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



11: Screen Front
Chipped
Over 10mm

12: Seat Base Cover of
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		