

VEHICLE INSPECTION REPORT

PN14WYK

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 08/04/2014

VIN XLRAEL1500L435428

Axle Combi 4x2

Year 2014

Body Style Box Van

Rear Suspension Steel

Mileage 966,563 Km Warranted

MOT Due 31/08/2026

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour RED

Gearbox MANUAL

Tyres


NSF NSI1 NSI2 NSI3 NSI4


OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
 Scratched
 25 to 100mm Thru Paint

4: Wing nsf
 Scratched
 Over 25mm Not Thru Paint



5: Other
 N/A
 N/A

6: Door Mirror Assy nsf
 Scuffed (Unpainted)
 Over 100mm



7: Door nsf
 Scratched
 UpTo 25mm Thru Paint

8: Other
 N/A
 N/A



9: Bumper Rear
Rusted
Over 5mm

10: Other
N/A
N/A



11: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

12: Door osf
Scratched
Over 25mm Thru Paint



13: Door osf
Chipped
Edge Chip

14: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	