

VEHICLE INSPECTION REPORT

YB17DWW

Ford Transit Custom 290 2.0 TDCI 105PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 21/06/2017

Year 2017

Mileage 101,636 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0YXXTTGYHM21665

Body Style Panel Van L1

MOT Due 09/07/2026

CAP Clean £3,975.00

CAP Average £3,325.00

CAP Below £2,450.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH AD-BLUE, TWIN SIDE LOAD DOOR, HEATED WINDSCREEN

Tyres

NSF

NSR

OSF


OSR



Spare

Features

- Bluetooth connection
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage




4: Door nsf
Dented
With Paint Damage



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Door nsf
Dented
With Paint Damage



7: Door nsr
Dented
Over 30mm

8: Door osr
Dented
Over 30mm



9: Door nsr
Dented
With Paint Damage



10: Door osr
Dented
With Paint Damage



11: Qtr Panel osr
Dented
With Paint Damage



13: Screen Front
Chipped
Over 10mm

12: Door osf
Dented
Over 30mm



14: Carpets Front
Holed
Over 3mm



15: Seat Base Cover nsf
Soiled
Heavy

16: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		