

VEHICLE INSPECTION REPORT

YC20EOW

Ford Transit Connect 240 1.5 ECOBLUE 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 25/03/2020

Year 2020

Mileage 62,263 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0SXXWPGSLB00319

Body Style Panel Van L2

MOT Due 08/09/2026

CAP Clean £6,350.00

CAP Average £5,575.00

CAP Below £4,450.00

Gearbox MANUAL

Gears 6

AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Qtr Panel nsr
Dented
Over 30mm

4: Bumper Rear
Cracked
Over 25mm



5: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		