

VEHICLE INSPECTION REPORT

YC20EOG

Ford Transit Connect 240 1.5 ECOBLUE 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 25/03/2020

Year 2020

Mileage 44,544 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0SXXWPGSLB00320

Body Style Panel Van L2

MOT Due 01/11/2026

CAP Clean £6,925.00

CAP Average £6,075.00

CAP Below £4,850.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH AD-BLUE, TWIN SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Bluetooth connection
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



3: Door nsf
Scratched
Over 25mm Thru Paint

4: Door nsf
Dented
Over 30mm



5: Qtr Panel nsr
Chipped
Multiple Chips

6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Seat Base Cover nsf
Soiled
Heavy

8: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	Fault		
ABS light illuminated	OK		