

VEHICLE INSPECTION REPORT

BX09GXS

Daf LF 45.160

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 24/08/2009

Colour WHITE

Cab Type DAY CAB

Year 2009

VIN XLRAE45FF0L353570

Gearbox MANUAL

Mileage 274,167 Km Warranted

Body Style MOBILE WORKSHOP

Axle Combi 4x2

Fuel Type Diesel

MOT Due 31/01/2027

Rear Suspension Steel

RACKING, STORAGE, WORKBENCH, KITCHENETTE, SEATING AREA

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4



OSO1 OSO2 OSO3 OSO4

Features

- Cruise control
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Rusted
Over 5mm

2: Panel Front
Scratched
Over 25mm Thru Paint



3: Door nsf
Scratched
Over 25mm Thru Paint

4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Qtr Panel Moulding ns
Scratched (Painted)
Over 25mm Thru Paint

6: Qtr Panel osr
Poor Previous Repair
Poor Paint



7: Door osf
Scratched
Over 25mm Thru Paint

8: Door Pad osf
Soiled
Heavy





9: In Car Entertainment
Missing
Replace

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		