

VEHICLE INSPECTION REPORT

PE15HHY

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	06/05/2015	VIN	XLRAEL1500L443330	Cab Type	DAY CAB
Year	2015	Body Style	Box Van	Gearbox	MANUAL
Mileage	645,983 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Steel
Colour	RED	MOT Due	30/11/2026	Tail Lift	Cantilever

COLLECTED AS NON-RUNNER, FAULTS ON MAINTANCE TEST, WARNING LIGHT ON DASH

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Qtr Panel osr
Cracked
Replace

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Panel Front
Poor Previous Repair
Rippled Up To 30%



4: Bonnet
Scratched
Over 25mm Thru Paint



5: Door osf
Scratched
Over 25mm Not Thru Paint



6: Screen Front
Chipped
Over 10mm

7: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault		