



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

CK25VKL

Vauxhall Vivaro 2.0 PRIME XL 145PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date	31/03/2025	VIN	VXEVLEHT2SZ015011	CAP Below	£17,300.00
Year	2025	Body Style	Crew Van MWB	Gearbox	MANUAL
Mileage	8,396 Miles Not Warranted	MOT Due	30/03/2028	Gears	6
Fuel Type	Diesel	CAP Clean	£20,000.00		
Colour	WHITE	CAP Average	£19,200.00		

OUTSTANDING RECALL TWIN LOADING DOORS, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows

Photos





Condition Check



Damage Photos



1: Screen Front
Chipped
UpTo 10mm

2: Bumper Front
Hole
Over 25mm



3: Wing nsf
Dented
Between 10mm + 30mm

4: Door nsf
Dented
Over 30mm



5: Door Moulding nsf
Missing
Replace

6: Qtr Panel nsr
Dented
Over 30mm



7: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm

8: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK