

VEHICLE INSPECTION REPORT

DK69ZGT

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 13/12/2019

VIN XLRTGM4100G292849

Axle Combi 6x2

Year 2019

Body Style Tractor Unit

Steering Combi Mid-Lift

Mileage 723,460 Km Warranted

MOT Due 31/10/2026

Rear Suspension Air

Fuel Type Diesel

Cab Type SPACE CAB

Colour WHITE

Gearbox AUTOMATIC

LIGHT WEIGHT AXLE

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3


OSO4

Features

- Cruise control
- Park assist camera
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Panel Rear
Dented
With Paint Damage

6: Door osf
Dented
With Paint Damage



7: Door osf
Scratched
Over 25mm Thru Paint

8: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		