

VEHICLE INSPECTION REPORT

CU65DYW

Ford Transit 350 2.2 TDCI 155PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	19/02/2016	VIN	WF0XXXTTGXFU71399	CAP Below	£2,100.00
Year	2016	Body Style	Panel Van L2	Gearbox	MANUAL
Mileage	109,531 Miles Warranted	MOT Due	18/02/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£3,575.00		
Colour	WHITE	CAP Average	£2,925.00		

RACKING, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres


NSF	
NSR	
OSF	Punctured
OSR	
Spare	

Features

- Bluetooth connection
- Digital radio
- Central locking
- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Auxiliary input socket
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Roof
Chipped
Multiple Chips

2: Bonnet
Chipped
Multiple Chips



3: Bumper Front
Scratched
Over 100mm Thru Paint

4: Door nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

6: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



7: Qtr Panel nsr
Dented
Over 30mm

8: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



9: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint

10: Qtr Panel osr
Dented
Over 30mm



11: Qtr Panel osr
Dented
With Paint Damage

12: Door osf
Dented
With Paint Damage



13: Wing Front Arch Extension os
Missing
Replace

14: Other
N/A
N/A



15: Screen Front
Chipped
Over 10mm

16: Door Pad osf
Soiled
Heavy



17: Carpets Front
Holed
Over 3mm

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Poor		Poor	
OK		No	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		