

VEHICLE INSPECTION REPORT

CU15GAX

Ford Transit 350 2.2 TDCI 155PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	15/06/2015	VIN	WF0XXXTTGXFD31993	CAP Below	£1,800.00
Year	2015	Body Style	Panel Van L3	Gearbox	MANUAL
Mileage	127,694 Miles Warranted	MOT Due	14/06/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£3,175.00		
Colour	WHITE	CAP Average	£2,575.00		

E/ MIRRORS, HEATED WINDSCREEN, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF

NSR

OSF

OSR




Spare


Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking


Photos







Condition Check




Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Door nsf
Chipped
Multiple Chips

4: Qtr Panel nsr
Dented
Over 30mm



5: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

6: Bumper Rear Moulding
Scuffed (Unpainted)
Over 100mm



7: Door nsr
Dented
Over 30mm

8: Qtr Panel osr
Dented
Over 30mm



9: Qtr Panel osr
Dented
With Paint Damage

10: Qtr Panel osr
Dented
Over 30mm



11: Qtr Panel osr
Dented
With Paint Damage

12: Qtr Panel osr
Dented
Over 30mm



13: Qtr Panel osr
Dented
Over 30mm

14: Door osf
Dented
With Paint Damage



15: Door osf
Dented
With Paint Damage

16: Seat Base Cover osf
Holed
Over 3mm



17: Seat Base Cover nsf
Soiled
Heavy

18: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		