

VEHICLE INSPECTION REPORT

CU67PXT

Ford Transit 350 2.0 TDCI 170PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	01/09/2017	VIN	WF0XXXTTGXHA14916	CAP Below	£3,625.00
Year	2017	Body Style	Panel Van L2	Gearbox	MANUAL
Mileage	86,370 Miles Warranted	MOT Due	31/08/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£5,875.00		
Colour	WHITE	CAP Average	£4,900.00		

AD-BLUE, E/ MIRRORS, RACKING, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF

NSR

OSF

OSR




Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Park assist camera
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Scratched
Over 25mm Thru Paint

4: Door Mirror Assy nsf
Broken
Replace



5: Qtr Panel nsr
Dented
With Paint Damage

6: Qtr Panel nsr
Dented
With Paint Damage



7: Qtr Panel nsr
Dented
Over 30mm

8: Qtr Panel nsr
Dented
Over 30mm



9: Wing osf
Scratched
Over 25mm Thru Paint

10: Carpets Front
Holed
Over 3mm



11: Seat Base Cover osf
Holed
Over 3mm

12: Seat Base Cover nsf
Soiled
Heavy



13: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		