

VEHICLE INSPECTION REPORT

CU15GBF

Ford Transit 350 2.2 TDCI 155PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	15/06/2015	VIN	WF0XXXTTGXFD31996	CAP Below	£1,675.00
Year	2015	Body Style	Panel Van L3	Gearbox	MANUAL
Mileage	144,410 Miles Warranted	MOT Due	14/06/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£2,950.00		
Colour	WHITE	CAP Average	£2,375.00		

E/ MIRRORS, HEATED WINDSCREEN, V5 NEW KEEPER DOCUMENT REFERENCE NUMBER AVAILABLE FOR TAXATION PURPOSES

Tyres

NSF

NSR

OSF


OSR



Spare

Features

- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Roof
Chipped
Multiple Chips



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Moulding
Missing
Replace

4: Door Mirror Assy nsf
Broken
Replace



5: Qtr Panel nsr
Dented
With Paint Damage

6: Qtr Panel nsr
Dented
Over 30mm



7: Qtr Panel nsr
Rusted
Over 5mm

8: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



9: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

10: Bumper Rear Moulding
Scuffed (Unpainted)
UpTo 100mm



11: Door nsr
Dented
With Paint Damage

12: Door osr
Dented
With Paint Damage



13: Qtr Panel osr
Dented
Over 30mm

14: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



15: Qtr Panel osr
Dented
With Paint Damage

16: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm



17: Qtr Panel osr
Dented
With Paint Damage

18: Door osf
Scratched
Over 25mm Thru Paint



19: Door Moulding osf
Scuffed (Unpainted)
Over 100mm

20: Door Mirror Assy osf
Broken
Replace



21: Door Pad osf
Soiled
Heavy

22: Seat Base Cover osf
Torn
Over 3mm



23: Seat Base Cover nsf
Soiled
Heavy

24: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		