

VEHICLE INSPECTION REPORT

NV14FZK

Ford Transit 350 2.2 TDCI 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 29/07/2014

Year 2014

Mileage 74,128 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXTTGXEJ15935

Body Style Panel Van L2

MOT Due 17/06/2026

CAP Clean £3,625.00

CAP Average £2,850.00

CAP Below £1,950.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH RACKING

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



5: Door osr
Dented
With Paint Damage

6: Door osr
Dented
With Paint Damage



7: Qtr Panel osr
Dented
With Paint Damage

8: Door Pad osf
Soiled
Heavy



9: Carpets Front
 Holed
 Over 3mm

10: Dash Warning Lights
 Displayed
 No Action

Interior

Carpet Condition		Poor	Upholstery Condition		Poor
Seat Condition		Poor	Odour		No
Engine Runs	OK		No Excessive Smoking	OK	
EML light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	Fault	