

VEHICLE INSPECTION REPORT

NV14XVR

Ford Transit 350 2.2 TDCI 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 29/07/2014

Year 2014

Mileage 52,635 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0XXXTTGX EJ15979

Body Style Panel Van L2

MOT Due Expired

CAP Clean £3,900.00

CAP Average £3,100.00

CAP Below £2,100.00

Gearbox MANUAL

Gears 6

SIDE LOAD DOOR, TOW BAR

Tyres

NSF

NSR

OSF

OSR



Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Door nsf
Dented
Over 30mm



3: Wing Front Arch Extension ns
Broken
Replace

4: Door nsf
Dented
Over 30mm



5: Door nsf
Chipped
Multiple Chips

6: Fuel Flap
Missing
Replace



7: Qtr Panel nsr
Dented
With Paint Damage

8: Qtr Panel nsr
Chipped
Multiple Chips



9: Qtr Panel nsr
Dented
With Paint Damage

10: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



11: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm

12: Qtr Panel nsr
Chipped
Multiple Chips



13: Door nsr
Dented
With Paint Damage

14: Door nsr
Scratched
Over 25mm Thru Paint



15: Door nsr
Chipped
Multiple Chips



16: Door osr
Dented
With Paint Damage




17: Door osr
Dented
With Paint Damage




18: Qtr Panel osr
Scratched
Over 25mm Thru Paint



19: Qtr Panel osr
Dented
Over 30mm



20: Qtr Panel osr
Dented
With Paint Damage





21: Qtr Panel osr
Dented
Over 30mm

22: Door osf
Chipped
Multiple Chips



23: Carpets Front
Holed
Over 3mm

24: Seat Base Cover osf
Holed
Over 3mm



25: Seat Base Cover nsf
Soiled
Heavy

26: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		