

# VEHICLE INSPECTION REPORT

**AY60DTZ**

## SCANIA P 420

### Inspection

### Vehicle

|     |                |
|-----|----------------|
| VAT | Plus VAT       |
| V5  | Buyer To Apply |

### Details

|           |                          |            |                   |                 |           |
|-----------|--------------------------|------------|-------------------|-----------------|-----------|
| Reg. date | 18/02/2011               | Colour     | BLUE              | Gearbox         | AUTOMATIC |
| Year      | 2011                     | VIN        | VLUP4X20009154438 | Axle Combi      | 4x2       |
| Mileage   | 853,803 Km Not Warranted | Body Style | Car Transporter   | Rear Suspension | Air       |
| Fuel Type | Diesel                   | Cab Type   | SLEEPER CAB       |                 |           |

3 PEDAL OPTICRUISE, C/W C318630 TRANSPORTER ENGINEERING TRI AXLE TRAILER, SAE DRUM AXLES, VIN : 110201517

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Digital radio
- Air conditioning

## Photos











