

VEHICLE INSPECTION REPORT

PF14TXY

Daf LF 150

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	21/08/2014	VIN	XLRAEL1500L437769	Gearbox	MANUAL
Year	2014	Body Style	Box Van	Axle Combi	4x2
Mileage	822,030 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	31/08/2026	Tail Lift	Column
Colour	RED	Cab Type	DAY CAB		

COLLECTED AS NON-RUNNER, REAR AXLES, SEATS, HALF SHAFT & REAR HUBS REQUIRE ATTENTION, WARNING LIGHT ON DASH


Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Moulding of Wing
Broken
Replace

2: Bonnet
Chipped
Multiple Chips



3: Door Mirror Assy nsf
Scratched (Painted)
Over 25mm Thru Paint

4: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



5: Other
N/A
N/A

6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Door nsf
Chipped
Multiple Chips

8: Door Mirror Assy osf
Scratched (Painted)
Over 25mm Thru Paint



9: Carpets Front
Holed
Over 3mm

10: Seat Base Cover osf
Holed
Over 3mm



11: Centre Console Front
Broken
Replace

12: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	Average
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	Fault
EML light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	Fault		