



**COMMERCIAL VEHICLE AUCTIONS LTD**  
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate  
Doncaster  
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

# VEHICLE INSPECTION REPORT

**EJ24XYP**

## Kia Sportage 1.6T GDI GT LINE

| Inspection      |    | Vehicle |                |
|-----------------|----|---------|----------------|
| Serious Damage? | No | VAT     | VAT Qualifying |
|                 |    | V5      | Buyer To Apply |

| Details   |                            |             |                   |           |            |
|-----------|----------------------------|-------------|-------------------|-----------|------------|
| Reg. date | 31/07/2024                 | VIN         | U5YPX81GMSL190839 | CAP Below | £22,600.00 |
| Year      | 2024                       | Body Style  | Hatchback         | Gearbox   | AUTOMATIC  |
| Mileage   | 15,092 Miles Not Warranted | MOT Due     | 30/07/2027        | Gears     | 6          |
| Fuel Type | Hybrid Electric            | CAP Clean   | £25,200.00        |           |            |
| Colour    | GREY                       | CAP Average | £23,850.00        |           |            |

KEYLESS IGNITION

|       |
|-------|
| Tyres |
| NSF   |
| NSR   |
| OSF   |
| OSR   |
| Spare |

## Features


- Front parking sensor
- Rear parking sensor
- Front electric windows
- Heated front seat
- Body coloured bumpers
- Leather seat trim
- Navigation system
- Electric door mirrors
- Alloy wheels
- Park assist camera
- Air conditioning

## Photos






|  |      |       |      |                     |
|--|------|-------|------|---------------------|
| TRANS  | AXLE | PAINT | TRIM | KIA SLOVAKIA S.R.O. |
| F  | H8   | WK    |      | e4*2018/858*00079   |
| 장비부호   |      |       |      | U5YPX81GMSL 190839  |
| SVC CODE   |      |       |      | 2175 kg             |
|  |      |       |      | 3535 kg             |
|  |      |       |      | 1 - 1260 kg         |
|  |      |       |      | 2 - 1200 kg         |
| Contact address: KIA SLOVAKIA S.R.O.                           |      |       |      |                     |
| Sv. Jana Nepomuckeho 1282/1. Teplicka nad Vahom. 013 01. Slova |      |       |      |                     |
| KIA UK Limited   |      |       |      |                     |
| Walton Green, Walton-on-Thames, Surrey KT12 1FJ, Great Brit    |      |       |      |                     |



## Condition Check



## Damage Photos



1: Screen Front  
Chipped  
UpTo 10mm



2: Door nsr  
Scratched  
Over 25mm Thru Paint



3: Door osf  
Dented  
With Paint Damage

### Interior

| Carpet Condition         | OK | Upholstery Condition                           | OK |
|--------------------------|----|--|----|
| Seat Condition           | OK | Odour  | No |
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake            | OK | Gearbox Static Gear Selection (engine running) | OK |
|                          |    | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | DPF light illuminated                          | OK |
| ABS light illuminated    | OK | Service indicator light illuminated            | OK |