

# VEHICLE INSPECTION REPORT

**RK69ZTN**

## Iveco Eurocargo 75-160

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	28/10/2019	VIN	ZCFA775B502692790	Axle Combi	4x2
Year	2019	Body Style	Box Van	Rear Suspension	Steel
Mileage	98,295 Km Warranted	MOT Due	30/11/2025	Rear Doors	Roller
Fuel Type	Diesel	Cab Type	DAY CAB	Tail Lift	Column
Colour	WHITE	Gearbox	AUTOMATIC		

\*WARNING LIGHT ON DASH\*

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

## Features

- Cruise control
- Radio/CD
- Front electric windows
- Cloth seat trim

## Photos












## Condition Check



## Damage Photos



1: Door nsf  
Dented  
Over 30mm



2: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint



3: Qtr Panel nsr  
 Scratched  
 Over 25mm Thru Paint



4: Qtr Panel nsr  
 Scratched  
 Over 25mm Thru Paint



5: Qtr Panel osr  
 Scratched  
 Over 25mm Not Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		