



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

MH24ZCN

Peugeot Partner 1.5 BLUEHDI 100PS PROFESSIONAL

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 31/07/2024

VIN VR3EDYHT4RJ777956

CAP Below £10,000.00

Year 2024

Body Style Panel Van SWB

Gearbox MANUAL

Mileage 19,801 Miles Not Warranted

MOT Due 30/07/2027

Gears 6

Fuel Type Diesel

CAP Clean £12,050.00

CAP Average £11,400.00

Colour WHITE

E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR



Spare

Features

- Rear parking sensor
- Air conditioning
- Front electric windows
- Central locking


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
UpTo 25mm Not Thru Paint

2: Panel Front
Scratched
UpTo 25mm Thru Paint



3: Panel Front
Chipped
Multiple Chips

4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Door Moulding osf
Scuffed (Unpainted)
Over 100mm

6: Seat Base Cover osf
Soiled
Light

Interior

Carpet Condition	-	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
Airbag light illuminated	OK	Oil warning light illuminated	OK
ABS light illuminated	OK	DPF light illuminated	OK
		Service indicator light illuminated	OK