

VEHICLE INSPECTION REPORT

RX24TEO

Carr Hill

Mercedes-Benz Sprinter 315 CDI PREMIUM

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Missing		
Details					
Reg. date	28/03/2024	VIN	W1V3HCFZ2PP593318	CAP Below	£19,800.00
Year	2024	Body Style	Panel Van LWB	Gearbox	MANUAL
Mileage	80,987 Miles Not	MOT Due	27/03/2027	Axle Combi	4x2
	Warranted	CAP Clean	£17,100.00		
Fuel Type	Diesel	CAP Average	£19,050.00		
Colour	BLACK		·		

A/C, AD-BLUE, SINGLE SIDE DOOR, FRONT & REAR SENSORS, E/WINDOWS & MIRRORS, REAR CAMERA

Tyres			
Tyres NSF			
NSR			
OSF			
OSR			
Spare			

Photos



















Condition Check



Damage Photos



1: Bonnet Chipped Multiple Chips



2: Door nsf Scratched Over 25mm Thru Paint



3: General Exterior Soiled Light



4: General Exterior Soiled Light



5: General Exterior Soiled Light



6: General Exterior Soiled Light



7: Door osf Scratched UpTo 25mm Thru Paint

Interior

Carpet Condition Seat Condition	OK OK		Upholstery Condition OK Odour No	
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake		OK	No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK