

VEHICLE INSPECTION REPORT

SF25XVN

Renault C 430

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 17/03/2025

Year 2025

Mileage 63,995 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN VF630S163SD006861

Body Style Tipper

MOT Due 01/04/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 8x4

Rear Suspension Steel

WEIGHTLIFTER TIPPER BODY, EDBRO TIPPING GEAR, AIR REAR DOOR, MID STEER, SHEETING SYSTEM.


Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD
- Air conditioning


Photos







Condition Check



Damage Photos



1: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



2: Qtr Panel or
Dented
With Paint Damage



3: Tailgate Trim Panel
Broken
Replace

4: Tailgate
Dented
With Paint Damage



5: Qtr Panel nsr
Dented
With Paint Damage

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		