

VEHICLE INSPECTION REPORT

PK67VFU

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 09/11/2017

Year 2017

Mileage 1,071,884 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G181979

Body Style Tractor Unit

Service history Yes

MOT Due 31/05/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2


OSO3






OSO4


Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Bonnet
Chipped
Multiple Chips

4: Screen Front
Chipped
Over 10mm



5: Bumper Front
Scratched
25 to 100mm Thru Paint

6: Wing nsf
Cracked
Replace



7: Door Mirror Assy nsf
Broken
Replace

8: Door nsf
Dented
Over 30mm



9: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Thru Paint



10: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



11: Door osf
Scratched
Over 25mm Thru Paint



12: In Car Entertainment
Broken
Replace



13: Switches And Controls
Broken
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	