

VEHICLE INSPECTION REPORT

PK67VHW

Daf CF 450

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 14/11/2017

Year 2017

Mileage 1,336,993 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G182203

Body Style Tractor Unit

Service history Yes

MOT Due 30/06/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift

Rear Suspension Air

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3



OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Wing osf
Chipped
Multiple Chips



2: Fog Lamp Surround os
Scratched (Painted)
Over 25mm Thru Paint



3: Bonnet
Chipped
Multiple Chips



4: Screen Front
Chipped
Over 10mm



5: Wing nsf
Chipped
Multiple Chips



6: Fog Lamp Surround ns
Scratched (Painted)
Over 25mm Thru Paint



7: Door Mirror Assy nsf
Broken
Replace



8: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Not Thru Paint





9: Wing Front Arch Extension os
Scratched (Painted)
Over 25mm Not Thru Paint

10: Door osf
Scratched
Over 25mm Thru Paint



11: Door osf
Dented
With Paint Damage

12: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



13: Switches And Controls
Broken
Replace

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK