

VEHICLE INSPECTION REPORT

DK17KWN

Man TGS 26.360

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow

Details

Reg. date	24/06/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMA18SZZ1HP088556	Gearbox	MANUAL
Mileage	265,650 Km Warranted	Body Style	Dropside & Crane	Axle Combi	6x2
Fuel Type	Diesel	MOT Due	31/03/2026	Rear Suspension	Air

SERVICE SCHEDULE LIST AVAILABLE, HMF 1420-K2 REMOTE CRANE (YEAR 2016), SURROUND CAMERA SYSTEM

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera


Photos







Condition Check



Damage Photos



1: Bumper Front
Dented
Over 30mm

2: Other
N/A
N/A



3: Wing osf
Scratched
Over 25mm Thru Paint

4: Bonnet
Chipped
Multiple Chips



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Other
N/A
N/A



7: Wing nsf
Scratched
Over 25mm Thru Paint

8: Other
N/A
N/A



9: Other
N/A
N/A

10: Other
N/A
N/A



11: Other
N/A
N/A

12: Bumper Rear
Rusted
Over 5mm



13: Other
N/A
N/A

14: Other
N/A
N/A



15: Other
N/A
N/A

16: Other
N/A
N/A



17: Door osf
Chipped
Edge Chip

18: Door Mirror Assy osf
Missing
Replace



19: Seat Base Cover osf
Holed
Over 3mm

20: Door Pad osf
Broken
Replace

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	