

VEHICLE INSPECTION REPORT

PE65UZX

Daf LF 220

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 21/10/2015

VIN XLRAEL3700L448385

Axle Combi 4x2

Year 2015

Body Style Box Van

Rear Suspension Steel

Mileage 1,198,069 Km
Warranted

MOT Due 30/04/2026

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour RED

Gearbox AUTOMATIC

COLLECTED AS NON-RUNNER, CORROSION, CLUTCH & INPUT SHAFT REQUIRE ATTENTION

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4






OSO1 OSO2 OSO3 OSO4

Features

- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Door osf
Scratched
Over 25mm Thru Paint



3: Seat Base Cover nsf
Holed
Over 3mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		