



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

FH17SDV

Fiat Ducato 35 2.3 MULTIJET 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Present

Details

Reg. date	08/08/2017	VIN	ZFA25000002B12605	CAP Below	£1,600.00
Year	2017	Body Style	Panel Van L3	Gearbox	MANUAL
Mileage	182,297 Miles Warranted	MOT Due	12/04/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£2,525.00		
Colour	WHITE	CAP Average	£2,125.00		

NO ACCESS TO SIDE DOOR TWIN LOADING DOORS, TOW BAR, E/MIRRORS


Tyres

NSF
NSR
OSF
OSR
Spare


Features

- Air conditioning
- Front electric windows

Photos



Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Other
N/A
N/A



3: Bumper Front
Dented
Over 30mm

4: Bumper Front Moulding
Scuffed (Unpainted)
Up To 100mm



5: Other
N/A
N/A

6: Fuel Flap
Scratched
Over 25mm Thru Paint



7: Other
N/A
N/A

8: Door nsr
Dented
With Paint Damage



9: Other
N/A
N/A

10: Seat Base Cover osf
Holed
Over 3mm



11: Carpets Front
Holed
Over 3mm

12: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK