

VEHICLE INSPECTION REPORT

BN14WSZ

Iveco Eurocargo 75E16

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	19/03/2014	VIN	ZCFA675BX02623161	Cab Type	DAY CAB
Year	2014	Body Style	Box Van	Gearbox	MANUAL
Mileage	552,505 Km Warranted	Service history	Yes	Axle Combi	4x2
Fuel Type	Diesel	Service documents	Printout	Rear Suspension	Steel
Colour	RED	MOT Due	31/08/2026	Tail Lift	Cantilever

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Cruise control
- Cloth seat trim
- Radio/CD
- Front electric windows
- Central locking


Photos








Condition Check



Damage Photos



1: Bonnet
Scratched
Over 25mm Thru Paint

2: Door nsr
Scratched
Over 25mm Thru Paint



3: Qtr Panel nsr
 Scratched
 Over 25mm Thru Paint

4: Qtr Panel osr
 Scratched
 Over 25mm Not Thru Paint



5: Qtr Panel osr
 Scratched
 Over 25mm Not Thru Paint

6: Door osf
 Scratched
 Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		