



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

DK17KWW

Man TGS 26.360

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details					
Reg. date	19/06/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMA18SZZ5HP088401	Gearbox	MANUAL
Mileage	196,746 Km Warranted	Body Style	Dropside & Crane	Axle Combi	6x2
Fuel Type	Diesel	MOT Due	28/02/2027		

HMF 1420K REMOTE CRANE (YEAR 2017), SURROUND CAMERA SYSTEM, SERVICE SCHEDULE LIST & LAST CRANE TEST AVAILABLE

Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera


Photos







Condition Check



Damage Photos



1: Wing of
Scratched
Over 25mm Not Thru Paint

2: Other
N/A
N/A



3: Bumper Front
Dented
Between 10mm + 30mm

4: Bonnet
Scratched
Over 25mm Not Thru Paint



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Other
N/A
N/A



7: Wing nsf
Scratched
Over 25mm Not Thru Paint

8: Door nsf
Scratched
Over 25mm Not Thru Paint



9: Other
N/A
N/A

10: Other
N/A
N/A



11: Bumper Rear
Rusted
Over 5mm

12: Other
N/A
N/A



13: Door osf
Scratched
Up To 25mm Thru Paint

14: Door osf
Scratched
Over 25mm Not Thru Paint



15: Other
N/A
N/A

16: Other
N/A
N/A

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK