

# VEHICLE INSPECTION REPORT

**ML24CZS**

## Renault Trafic LL30 DCI 170PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 To Follow

### Details

Reg. date 04/03/2024

Year 2024

Mileage 41,891 Miles  
Warranted

Fuel Type Diesel

Colour GREY

VIN VF1JL000X72268837

Body Style Minibus

MOT Due 03/03/2027

Gearbox AUTOMATIC

Gears 6

\*OIL LEAK\* AD-BLUE, TWIN LOADING DOORS, E/MIRRORS

### Tyres

NSF

NSR

OSF


OSR

Spare

## Features

- Rear parking sensor
- Air conditioning
- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Scratched  
Over 25mm Not Thru Paint



2: Bonnet  
Chipped  
Multiple Chips



3: Bumper Front  
Scratched  
25 to 100mm Thru Paint

4: Door Mirror Assy nsf  
Scratched (Painted)  
Over 25mm Not Thru Paint



5: Qtr Panel nsr  
Scratched  
Over 25mm Not Thru Paint

6: Door osr  
Dented  
Over 30mm



7: Door osf  
Dented  
Between 10mm + 30mm

## Interior

|                          |    |                                                |    |
|--------------------------|----|------------------------------------------------|----|
| <b>Carpet Condition</b>  | OK | <b>Upholstery Condition</b>                    | OK |
| <b>Seat Condition</b>    | OK | <b>Odour</b>                                   | No |
| Engine Runs              | OK | Gearbox 1st and Reverse Test                   | OK |
| Brakes                   | OK | Clutch Slip Test from Static                   | OK |
| Parking Brake            | OK | Gearbox Static Gear Selection (engine running) | OK |
|                          |    | No Excessive Smoking                           | OK |
| EML light illuminated    | OK | Oil warning light illuminated                  | OK |
| Airbag light illuminated | OK | DPF light illuminated                          | OK |
| ABS light illuminated    | OK | Service indicator light illuminated            | OK |