

VEHICLE INSPECTION REPORT

S1FGT

Daf XG 530

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	10/11/2022	VIN	XLRTGF5300G419796	Axle Combi	6x2
Year	2022	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Mileage	455,553 Km Warranted	MOT Due	30/11/2026	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	SLEEPER CAB		
Colour	WHITE	Gearbox	AUTOMATIC		

WARNING LIGHTS ON DASH, POTENTIAL AIR LEAK SLIDING 5TH WHEEL, MIRROR CAMS, SURROUND CAMERA SYSTEM


Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4




Features

- Park assist camera
- Air conditioning


Photos







Condition Check



Damage Photos



1: Fog Lamp Surround is Scratched (Painted) Over 25mm Thru Paint



2: Bumper Front Cracked Over 25mm



3: Qtr Panel osr
Dented
With Paint Damage

4: Qtr Panel osr
Dented
With Paint Damage

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK