

VEHICLE INSPECTION REPORT

DG17XAH

Man TGM 18.250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date	30/08/2017	Colour	BLUE	Cab Type	DAY CAB
Year	2017	VIN	WMAN08ZZ6HY364297	Gearbox	MANUAL
Mileage	116,925 Km Warranted	Body Style	Dropside & Crane	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/11/2026	Rear Suspension	Steel

SERVICE SCHEDULE LIST AVAILABLE, HMF 1420K REMOTE CRANE (YEAR 2017), SURROUND CAMERA SYSTEM


Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Park assist camera


Photos







Condition Check



Damage Photos



1: Wing osf
Scratched
Over 25mm Thru Paint



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

4: Door Mirror Assy nsf
Missing
Replace



5: Other
N/A
N/A

6: Other
N/A
N/A



7: Other
N/A
N/A

8: Bumper Rear
Rusted
Over 5mm



9: Other
N/A
N/A

10: Other
N/A
N/A



11: Door osf
Scratched
Over 25mm Thru Paint

12: Door osf
Dented
With Paint Damage



13: Door osf
Chipped
Edge Chip

14: Other
N/A
N/A



15: Other
N/A
N/A

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs		OK		Gearbox 1st and Reverse Test		OK	
Brakes		OK		Clutch Slip Test from Static		OK	
Parking Brake		OK		Gearbox Static Gear Selection (engine running)		OK	
				No Excessive Smoking		OK	
EML light illuminated		OK		Oil warning light illuminated		OK	
Airbag light illuminated		OK		DPF light illuminated		OK	
ABS light illuminated		OK		Service indicator light illuminated		OK	