

VEHICLE INSPECTION REPORT

KV71YGW

Jaguar I-Pace EV400 HSE

Inspection

Serious Damage? No

Vehicle

VAT VAT Qualifying

V5 Buyer To Apply

Details

Reg. date 01/09/2021

Year 2021

Mileage 67,096 Miles Not Warranted

Fuel Type Electric

Colour GREY

VIN SADHA2A12M1617360

Body Style Hatchback

MOT Due Expired

CAP Clean £14,400.00

CAP Average £13,200.00

CAP Below £11,950.00

Gearbox AUTOMATIC

Gears 1

Doors 5

E/MIRRORS, KEYLESS IGNITION

NO CHARGING LEAD

Tyres

NSF

NSR

OSF

OSR





Spare


Features

- Bluetooth connection
- Navigation system
- Digital radio
- Radio/CD Multichanger
- Metallic Paint
- Leather seat trim
- Cruise control
- Park assist camera
- Mobile phone App interface
- Air conditioning
- Drivers airbag
- Front parking sensor
- Rear parking sensor
- Radio/Cassette
- Front electric windows
- Passenger airbag
- Heated front seat
- Auxiliary input socket
- Radio/CD
- Rear electric windows
- Central locking

Photos










Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 25mm Not Thru Paint

2: Bumper Front
Scratched
UpTo 25mm Not Thru Paint



3: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

4: Door nsr
Scratched
Over 25mm Not Thru Paint



5: Door nsf
Scratched
UpTo 25mm Not Thru Paint

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
OK		OK	
Average		No	
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK
Sat nav	OK		