

VEHICLE INSPECTION REPORT

DU23FNG

Volkswagen Crafter CR35 2.0 TDI 140PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 31/05/2023

Year 2023

Mileage 87,437 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN WV1ZZZSY2P9047353

Body Style Panel Van MWB

MOT Due 30/05/2026

CAP Clean £16,350.00

CAP Average £15,150.00

CAP Below £13,050.00

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH SIDE LOAD DOOR, E/MIRRORS, AD-BLUE.

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Rear parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Sill os
Scratched
Over 25mm Thru Paint



3: Roof
Dented
With Paint Damage

4: Bumper Front Moulding
Broken
Replace



5: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm

6: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



7: Door osf
Dented
Over 30mm

8: Qtr Panel osr
Dented
With Paint Damage



9: Qtr Panel Moulding os
Scuffed (Unpainted)
Over 100mm

10: Bumper Rear Moulding
Broken
Replace



11: Fog Lamp osr
Broken
Replace

12: Tailgate
Dented
With Paint Damage




13: Badgedecal Rear
Broken
Replace

14: Bumper Rear Moulding
Missing
Replace



15: Qtr Panel nsr
Dented
With Paint Damage

16: Door nsr
Dented
Over 30mm



17: Sill ns
Dented
With Paint Damage

18: Qtr Panel Moulding ns
Scuffed (Unpainted)
Over 100mm



19: Door nsf
Dented
Over 30mm

20: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		Fault	Oil warning light illuminated		OK
Airbag light illuminated		OK	Service indicator light illuminated		OK
ABS light illuminated		OK			
Windows		OK	Radio		OK
			Steering		OK