

VEHICLE INSPECTION REPORT

YC23XHE

Mercedes-Benz Vito Tourer 114 CDI

Inspection

Serious Damage? No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	49771
Cap Code	MEVI2014P6YDTA2 6 L

Details

Location	Bedford	Colour	SILVER	CAP Average	£25,050.00
Reg. date	27/04/2023	VIN	W1VVKGFZ1P4239115	CAP Below	£21,600.00
Year	2023	Body Style	Minibus	Gearbox	AUTOMATIC
Mileage	53,536 Miles Not Warranted	MOT Due	Expired	Gears	9
Fuel Type	Diesel	CAP Clean	£27,050.00		

TWIN SIDE LOADING DOORS, AD BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Air conditioning
- Front electric windows
- Leather seat trim

Photos





Condition Check



Damage Photos



1: Qtr Panel nsr
Dented
Over 30mm



2: Qtr Panel nsr
Dented
With Paint Damage



3: Qtr Panel nsr
Dented
With Paint Damage



4: Tailgate
Dented
Between 10mm + 30mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK