

VEHICLE INSPECTION REPORT

C342619

SDC CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2013	Colour	BLUE	Axle Combi	Tri
Year	2013	VIN	SDCCS45S300121001	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn
Fuel Type		Brakes	Disc		

SAF AXLES, SHEETING SYSTEM, RAISE & LOWER VALVE, FERRY LASHING RINGS, SLIDING ROOF

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





