

VEHICLE INSPECTION REPORT

GO67ASM

Daf CF 370

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 14/09/2017

Year 2017

Mileage 390,591 Km Not Warranted

Fuel Type Diesel

Colour RED

VIN XLRASM4100G149982

Body Style Car Transporter

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Rear-Lift Steer

Rear Suspension Air

WARNING LIGHTS ON DASH SPEC LIFT, BELLE 6/7 CAR BODY, SALVAGE SPEC,, WINCH

Tyres

NSF NSI1

OSF OSI1

Spare NSO1

NSI2

OSI2

NSO2

OSO1

NSI3

OSI3

NSO3

OSO2

NSI4

OSI4

NSO4



OSO3

Features

- Air conditioning


Photos







Condition Check



Damage Photos



1: Wing osf
Cracked
Replace



2: Headlamp Washer os
Broken
Replace



3: Bumper Front
Chipped
Multiple Chips



4: Bonnet
Chipped
Multiple Chips



5: Wing nsf
Cracked
Replace



6: Bumper Front
Dented
With Paint Damage



7: A Post ns
Scratched
UpTo 25mm Thru Paint

8: A Post ns
Scratched
UpTo 25mm Thru Paint



9: B Post os
 Scratched
 UpTo 25mm Thru Paint

10: Door osf
 Dented
 Between 10mm + 30mm

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	Fault		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	