

VEHICLE INSPECTION REPORT

SJ23GFO

Volvo FM 460

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	12/04/2023	VIN	YV2XTY0CXP313582	Gearbox	AUTOMATIC
Year	2023	Body Style	Dropside & Crane	Axle Combi	6x2
Mileage	78,960 Km Not Warranted	Keys	2	Rear Suspension	Air
Fuel Type	Diesel	MOT Due	30/04/2026		
Colour	WHITE	Cab Type	DAY CAB		

PALFINGER PK 19001 REMOTE CRANE (YEAR 2022), PALFINGER BRICK GRAB



Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Cruise control
- Navigation system
- Air conditioning
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bumper Front
Scratched
25 to 100mm Thru Paint



2: Door Moulding osf
Scratched (Painted)
Over 25mm Thru Paint



3: Door nsf
 Scratched
 Over 25mm Thru Paint

4: Qtr Panel osr
 Scratched
 Over 25mm Thru Paint



5: Qtr Panel nsr
 Dented
 With Paint Damage

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK