

VEHICLE INSPECTION REPORT

C355319

DON-BUR BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2013	Colour		Axle Combi	Tri
Year	2013	VIN	SEPBV38GKDL061818	Rear Doors	Roller
Mileage	Not Showing	Body Style	Trailer		
Fuel Type		Brakes	Drum		

BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF
NSR
OSF
OSR
Spare

Photos



