



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

BT15TMY

Iveco Daily 70-170

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Present

Details			
Reg. date	15/06/2015	Fuel Type	Diesel
Year	2015	Colour	WHITE
Mileage	119,612 Km Warranted	VIN	ZCFC270C505011968
		Body Style	Panel Van
		Gearbox	MANUAL

WARNING LIGHTS ON DASH TOW BAR, SIDE LOAD DOOR



Tyres				
NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim
- Drivers airbag
- Passenger airbag


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Screen Front
Chipped
Over 10mm



3: Bumper Front
Cracked
Over 25mm

4: Bumper Front
Chipped
Over 5mm




5: Moulding nsf Wing
Scuffed (Unpainted)
Over 100mm

6: Wing nsf
Dented
With Paint Damage



7: Door nsf
Scratched
Up To 25mm Thru Paint

8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint

10: Qtr Panel nsr
Rusted
Over 5mm



11: Panel Rear
Scratched
Rusted

12: Bumper Front Moulding
Broken
Replace



13: Door nsr
Rusted
Over 5mm

14: Door osr
Rusted
Over 5mm



15: Panel Rear
Dented
With Paint Damage

16: Panel Rear
Scratched
Rusted



17: Qtr Panel osr
Chipped
Over 5mm

Interior

Carpet Condition
Seat Condition

OK
OK

Upholstery Condition
Odour

OK
-

Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK		
ABS light illuminated	OK		