



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

2625578

Iveco Eurocargo 180E25

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date	25/08/2014	VIN	ZCFA61TJX02625578	Axle Combi	4x2
Year	2014	Body Style	Box Van	Rear Suspension	Steel
Mileage	147,729 Km Warranted	MOT Due	30/09/2026	Rear Doors	Roller
Fuel Type	DIESEL	Cab Type	DAY CAB	Tail Lift	Column
Colour	WHITE	Gearbox	AUTOMATIC		

MOD 654 FORM IN OFFICE

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features


- Air conditioning

Photos





Condition Check



Damage Photos



1: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



2: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



3: Qtr Panel nsr
Scratched
Over 25mm Thru Paint

4: Qtr Panel osr
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm

6: Wing Front Arch Extension os
Scratched (Painted)
UpTo 25mm Thru Paint



7: Panel Front
Cracked
Replace

8: Centre Console Front
Broken
Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK