

VEHICLE INSPECTION REPORT

C293072

SDC CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/06/2010	Colour	BLUE	Axle Combi	Tri
Year	2010	VIN	SDCPL45R300105931	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn
Fuel Type		Brakes	Drum		

ROR AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





