

VEHICLE INSPECTION REPORT

YR69HKA

Ford Transit 350 2.0 TDCi 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	18/11/2019	VIN	WF0DXXTTGDKE34362	CAP Below	£4,675.00
Year	2019	Body Style	Dropside	Gearbox	MANUAL
Mileage	153,267 Km TBC	MOT Due	12/10/2026	Gears	6
Fuel Type	Diesel	CAP Clean	£6,950.00		
Colour	WHITE	CAP Average	£6,000.00		

WARNING LIGHTS ON DASH, NO BRAKES XLWB, TOW BAR, REAR VIEW CAMERA, AD-BLUE.

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Radio/CD
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Seat Base Cover of
Torn
Over 3mm



2: Sill of
Rusted
Over 5mm



3: Bonnet
Dented
Over 30mm

4: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



5: Door osf
Dented
Over 30mm

6: B Post os
Dented
Over 30mm



7: Qtr Panel osr
Dented
Over 30mm

8: Tailgate
Rusted
Over 5mm



9: Qtr Panel nsr
Dented
With Paint Damage

10: Door nsf
Dented
With Paint Damage

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	Fault		Clutch Slip Test from Static	OK
Turbo Boosting	Fault		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	Fault		No Excessive Smoking	Fault
EML light illuminated	Fault		Oil warning light illuminated	OK
Airbag light illuminated	OK		Service indicator light illuminated	OK
ABS light illuminated	Fault			
Windows	OK		Radio	OK
			Steering	OK