

VEHICLE INSPECTION REPORT

AE68ZRF

Ford Transit Connect 220 1.5 ECOBLUE 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 28/09/2018

Year 2018

Mileage 155,965 Miles
Warranted

Fuel Type Diesel

Colour SILVER

VIN WF0RXXWPGRJM12890

Body Style Panel Van L1

CAP Clean £3,550.00

CAP Average £3,000.00

CAP Below £2,275.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOADING DOOR

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Park assist camera
- Rear parking sensor
- Front electric windows

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips

2: Glove Box Lid
Broken
Replace



3: Bumper Rear
 Dented
 Between 10mm + 30mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Parking Brake		OK	Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated		OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK