

# VEHICLE INSPECTION REPORT

**GF63ZKB**

## Daf XF 460

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Buyer To Apply

### Details

Reg. date 11/02/2014

Year 2014

Mileage 913,560 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN XLRTGH4300G018277

Body Style Tractor Unit

Cab Type SUPER SPACE CAB

Gearbox AUTOMATIC

Steering Combi Mid-Lift Steer

Rear Suspension Air

\*WARNING LIGHT ON DASH\* SILIDING 5TH WHEEL



### Tyres





| NSF   | NSI1 | NSI2 | NSI3 | NSI4 |
|-------|------|------|------|------|
| OSF   | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
|       | OSO1 | OSO2 | OSO3 | OSO4 |

## Features

- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips

2: Panel Front  
Cracked  
Replace



3: Bumper Front  
Chipped  
Multiple Chips

4: Panel Front  
Scratched  
Over 25mm Thru Paint



5: Door Mirror Assy nsf  
Broken  
Replace

6: Wing nsf  
Cracked  
Replace



7: Qtr Panel Trim ns  
Broken  
Replace

8: Qtr Panel Moulding os  
Broken  
Replace



9: Qtr Panel osr  
 Scratched  
 Over 25mm Thru Paint

10: Door osf  
 Scratched  
 Over 25mm Thru Paint



11: Seat Base Cover nsf  
 Soiled  
 Heavy

12: Dash Warning Lights  
 Displayed  
 No Action

Interior

|                         |       |                             |    |
|-------------------------|-------|-----------------------------|----|
| <b>Carpet Condition</b> | OK    | <b>Upholstery Condition</b> | OK |
| <b>Seat Condition</b>   | Poor  | <b>Odour</b>                | -  |
| Engine Runs             | OK    | No Excessive Smoking        | OK |
| EML light illuminated   | Fault |                             |    |
| ABS light illuminated   | Fault |                             |    |