

VEHICLE INSPECTION REPORT

YS67VDG

Ford Transit Custom 290 2.0 TDCi 105PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 11/12/2017

Year 2017

Mileage 57,081 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN WF0YXXTTGYHK87502

Body Style Panel Van L1

MOT Due 22/10/2025

Gearbox MANUAL

Gears 6

WARNING LIGHT ON DASH AD-BLUE, SIDE LOAD DOOR, ROOF RACK

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim

Photos



Condition Check



Damage Photos



1: Bumper Front
Scratched
Over 100mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Door Moulding nsf
Missing
Replace



4: Qtr Panel osr
Dented
Over 30mm



5: Seat Base Cover nsf
Soiled
Heavy



6: Seat Base Cover osf
Soiled
Heavy



7: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK		