

VEHICLE INSPECTION REPORT

YA14VYK

Renault Kangoo Maxi ENERGY 90 DCI

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 24/07/2014

VIN VF1FW58H550995846

CAP Below £1,050.00

Year 2014

Body Style Panel Van LWB

Gearbox MANUAL

Mileage 77,444 Miles
Warranted

MOT Due 23/07/2025

Gears 5

Fuel Type Diesel

CAP Clean £1,825.00

Colour WHITE

CAP Average £1,475.00

TWIN SIDE LOAD DOOR, ROOF RACK, E/ MIRRORS, PIPE STORAGE (WITH KEYS)

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Drivers airbag
- Auxiliary input socket
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Wing nsf
Cracked
Replace



3: Door nsf
Dented
Over 30mm



4: Qtr Panel nsr
Dented
Over 30mm



5: Door nsr
Chipped
Multiple Chips



6: Qtr Panel osr
Dented
Over 30mm



7: Wing osf
Cracked
Replace



8: Screen Front
Scratched
Over 30mm



9: Door Pad osf
Soiled
Heavy



10: Seat Base Cover osf
Soiled
Heavy



11: Fascia Panel
Soiled
Heavy



12: Door Pad nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	Poor
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		