

VEHICLE INSPECTION REPORT

C268276

SDC CURTAINSIDE

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/10/2008	Colour	BLUE	Axle Combi	Tri
Year	2008	VIN	SDCPL45R300100259	Rear Suspension	Air
Mileage	Not Showing	Body Style	Trailer	Rear Doors	Barn
Fuel Type		Brakes	Drum		

ROR AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS, FORKLIFT BRACKET

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





